



Rockville Campus – Student Services
Asbestos Survey map updates December 2007

NOTE: Room numbers and configuration have changed since the surveys performed in 1988 and 1992.
A current floor plan is provided to help identify locations.



LIST OF MATERIALS

- FT1A -- 12x12 Floor Tile - Taupe w/beige and white flecks
- FT1B -- 12x12 Floor Tile - Off-white w/beige and white flecks
- FT2 -- 9X9 Floor Tile - Grey w/light and dark strips
- DW -- Drywall
- DWC -- Drywall Ceiling
- SPJ -- Speckled Pipe Joint
- BTWP -- Black Tar Wrap on Foil Duct Insulation
- BTWP -- Black Tar Wrap on Pipe Insulation
- CT1A -- Ceiling Tile 12x12 - Fissures close together
- CT1B -- Ceiling Tile 12x12 - Fissures further apart
- CT3A -- Ceiling Tile 24x48 - Fissures run vertically
- CT3B -- Ceiling Tile 24x48 - Fissures run horizontally
- CT3C -- Ceiling Tile 24x48 - Circular perforations
- CT3D -- Ceiling Tile 24x48 - Vertical fissures and perforations (Newer ceiling - Armstrong Brand)
- P/W -- Plaster Wall
- PC -- Plaster Ceiling



- ◇ Negative Sample
- ◇ Positive Sample

Summary of sample analysis June 1992

Montgomery College
 District Administration
 500 W. 10th Street
 Rockville, MD 20850
 Phone: (301) 782-1000

Project No. **97016**
 Project Name **RENOVATION OF THE STUDENT SERVICES BUILDING**

Contract No. **97016**
 Contract Date **5/20/92**

