


Rockville Campus – Humanities Building  
Asbestos Survey map update November 2001

The Humanities Building was renovated in 2001. All identified ACM was removed with the exception of sprayed-on fireproofing on perimeter structural supports and floor tile adhesive throughout the building.







ASBESTOS-CONTAINING SPRAY-ON FIREPROOFING LOCATED BEHIND VERTICAL STRUCTURAL STEEL (BETWEEN REAR OF COLUMN AND OUTSIDE WALL). UNABLE TO REMOVE DURING RENOVATION. ENCLOSED WITHIN HILTI FOAM.

SPRAY ON FIREPROOFING (OVERSPRAY) LOCATED UNDER WINDOW SILL (SPECIFICALLY IN THE SPACE BETWEEN INTERIOR CMU AND EXTERIOR PLASTER PANEL BELOW WINDOW) AIR SPACE ENCLOSED WITH HILTI FOAM.

**Montgomery College**  
 Central Administration  
 Office of Planning  
 600 Hampshire Drive  
 Rockville, MD 20850  
 Telephone: (301) 251-7383

Drawn By: M. Simpson	Chk. By:
Designed By:	Approved By:
Notes	

No.	Description	Date
Revisions		
Location Map		

Project Title: **Rockville Campus**  
**Humanities Building**

Drawing Title:  
**First Floor Plan**  
**Spray-On Fireproofing**

Scale: **Not To Scale**

Project No. \_\_\_\_\_ Drawing Number \_\_\_\_\_

Date: **11/01** **SOF-2**

P:\Acad\Drawings\Revised Master Drawings\Rockville-Revised/R--Humanities/Humanities Floor Plan Deigs/Hum\_Absbestos.dwg









